

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

393
WSW
1/2-1
0.634 mi.
3346 ft.

CAREY GARDENS II -NYCHA
2832 WEST 23RD ST
BROOKLYN, NY

NY LTANKS
NY Spills
S105230039
N/A

Relative:
Higher

Actual:
1 ft.

LTANKS:

Name: CAREY GARDENS II -NYCHA
Address: 2832 WEST 23RD ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9315471 / 2003-10-27
Facility ID: 9315471
Site ID: 62465
Spill Date: 1991-01-31
Spill Cause: Tank Test Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: C3
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: JAKOLLEE
Referred To: Not reported
Reported to Dept: 1994-03-30
CID: Not reported
Water Affected: Not reported
Spill Notifier: DEC
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1994-04-05
Spill Record Last Update: 2005-01-31
Spiller Name: Not reported
Spiller Company: NYCHA - JOE MONTELLA
Spiller Address: Not reported
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 219485
DEC Memo: ""
Remarks: "LEAK RATE OF 0.06 GPH REPORTED AS PASSED BY TESTER."

All TTF:

Facility ID: 9315471
Spill Number: 9315471
Spill Tank Test: 1542577
Site ID: 62465
Tank Number: 001
Tank Size: 0
Material: 0001
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 00
Test Method 2: Unknown
Leak Rate: .00
Gross Fail: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Modified By:
Last Modified Date:

Spills
Not reported

All Materials:

Site ID: 62465
Operable Unit ID: 993571
Operable Unit: 01
Material ID: 387222
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: -1.00
Units: L
Recovered: .00
Oxygenate: Not reported

SPILLS:

Name: CAREY GARDENS -NYCHA
Address: 2832 WEST 23RD ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0107804 / 2014-07-16
Facility ID: 0107804
Facility Type: ER
DER Facility ID: 219485
Site ID: 269490
DEC Region: 2
Spill Cause: Unknown
Spill Class: B3
SWIS: 2401
Spill Date: 2001-10-31
Investigator: JKKANN
Referred To: Not reported
Reported to Dept: 2001-10-31
CID: 270
Water Affected: Not reported
Spill Source: Private Dwelling
Spill Notifier: Local Agency
Cleanup Ceased: Not reported

Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2001-10-31
Spill Record Last Update: 2014-07-16
Spiller Name: CALLER
Spiller Company: NYC HOUSING AUTHORITY
Spiller Address: 23-02 49TH AVE
Spiller Company: 001
Contact Name: CALLEER
DEC Memo:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was
KOLLEENY 11/01/2001: TOM HALL TELCON WITH NORMAN SEBOWSKI-NYCHA
(718-707-5725) AT 1050 HRS. SEBOWSKI WILL HAVE MARIO MANDALONE UPDATE
DEPARTMENT AS TO PROGRESS OF WORK. 11/01/2001: TOM HALL TELCON WITH
MARIO MANDALONE AT 1510 HRS. 15K BEING REMOVED AND REPLACED WITH
ANOTHER 15K. MODERATE CONTAMINATION ENCOUNTERED IN EXCAVATION.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HORIZONTAL EXTENT OF CONTAMINATION SEEMS MINIMAL. VERTICAL EXTENT WILL BE DETERMINED. HOUSING AUTHORITY WILL SUBMIT CLOSURE DOCUMENTATION. 02/14/02 Reassigned from Hall (Region 7) to Kolleeny. 11/07/05: This spill transferred from J.Kolleeny to S.Kraszewski. 01/27/06: This spill transferred from S.Kraszewski to Q.Abidi. 03/31/06: This spill transferred from Q. Abidi to Koon Tang. 6/11/09: JKann - Spill transfered to J.Kann. Meeting held on 5/28 with ALC Environmental and NYCHA. Investigative Work Plan submitted on June 10, 2009. 01/28/2010: Remediation and other associated clean-up activities linked to this spill number is now under the oversight of Moses Ajoku, all correspondence related this case should be addressed to me. (MA) 7/15/13: J.Kann - spill transferred from Moses Ajoku to J.Kann. 10/15/13: J.Kann - after reviewing the file, minimal impacts have been noted at this site. The 1996 investigation yielded not impacts to soil or groundwater. During tank removal (as stated above) some impacts to soil were noted. I requested any information on the tank removal from NYCHA today via an email. After receiving a response from them, I will likely request that the two remaining wells be gauged and sampled so the site can be reviewed for closure. 6/13/14: J.kann - received a response from NYCHA. Some lab data was submitted for soil disposal during tank removal work on 10/16/13. In addition, NYCHA responded that a mobile boiler is in place at the site and much sand was washed up into the area as a result of Hurricane Sandy. Therefore, the two older wells are not accessible. I am considering site for closure. 7/16/14: J.Kann - received the RIR for the site on 6/25/14. 3 borings were advanced and 2 monitoring wells installed. Soil analysis was below CP-51 RSCOs. On constituent, naphthalene was detected in groundwater at 12ppb (TOGS guidance of 10ppb), otherwise all gw analysis was below TOGS 1.1.1. Reviewed report. Spill closed."

Remarks: "contaminated soil discovered from tank removal"

All Materials:

Site ID: 269490
Operable Unit ID: 845047
Operable Unit: 01
Material ID: 529066
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: CAREY GARDENS -NYCHA
Address: 2832 WEST 23RD ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0401274 / 2005-11-07
Facility ID: 0401274
Facility Type: ER
DER Facility ID: 219485
Site ID: 269491
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 2401
Spill Date: 2004-05-06

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Investigator: SWKRASZE
Referred To: Not reported
Reported to Dept: 2004-05-06
CID: 403
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2004-05-06
Spill Record Last Update: 2005-11-07
Spiller Name: NORMAN ZABUSKI
Spiller Company: Not reported
Spiller Address: 2832 WEST 23RD ST
Spiller Company: 001
Contact Name: NORMAN ZABUSKI
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was KOLLEENY 11/02/05: This spill transferred from J.Kolleeny to S.Kraszewski. "
Remarks: "mechanical failure on a portable boiler on the fitting. spill has been cleaned up"

All Materials:

Site ID: 269491
Operable Unit ID: 883114
Operable Unit: 01
Material ID: 492488
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 10.00
Units: G
Recovered: 10.00
Oxygenate: Not reported